

Incident #	INC-2020-002-PAR-OA-2018-004	
Incident occurred on:	February 12, 2020	
OA/ACW #:	ACW-2018-009	
Operator:	Paramount Resources Ltd.	
Location:	Bovie J-76 Well Site (Vicinity of Fort Liard NT)	
Summary of incident:	Equipment failure causing injury to worker	
Incident reported to OROGO by the operator on:	February 12, 2020	
Incident reported to NT-NU Spill Line (if required) on:	N/A	
Operator Follow-up Investigation Report:	Due: Mar. 4, 2020 Received:	
Status:	<p>Feb. 12, 2020: Due to equipment failure, a worker was struck and knocked down and is being assessed by a medical professional.</p> <p>Additional information will be provided to OROGO within the next 48 hours.</p> <p>WSCC has been notified of the incident.</p> <p>Follow-up investigation report due on or before March 4, 2020</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.