

Incident #	NM-2020-001-PAR-OA-2018-004	
Near-miss occurred on:	February 9, 2020	
OA/ACW #:	ACW-2018-009	
Operator:	Paramount Resources Ltd.	
Location:	Bovie J-76	
Summary of incident:	Diesel sprayed worker – No Injury	
Incident reported to OROGO by the operator on:	February 9, 2020 (In person on site)	
Status:	<p>Feb. 9, 2020: During fuel transfer operations between a fuel truck and stationary site tank, using a large volume hose, a worker was sprayed with diesel fuel but it was not ingested or come into contact with their eyes.</p> <p>The worker was given the opportunity to clean up and change into clean PPE.</p> <p>Visual inspection did not identify any release of a pollutant to the ground.</p> <p>This near-miss was caused by lack of experience of the worker and lack of direction by fuel supplier.</p> <p>Site staff addressed the fuel issue with the fuel supplier and re-trained staff on proper fuel handling procedures.</p> <p>Additionally, fuel delivery procedures were changed so that refuelling out of the fuel delivery truck, with a large volume hose, was minimized.</p> <p>No further action required - File Closed</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.