

John Hawkins
Director Asset Management
Paramount Resources Ltd
Suite 2800, 421 – 7 AVE SW
CALGARY AB T2P 4K9

June 25, 2020

Dear John Hawkins:

Well Status:

Abandonment of the Bovie J-76 Well (ACW-2018-009-PAR-J-76-WID1931)

On June 1, 2020, the Office of the Regulator of Oil and Gas Operations (OROGO) received the Well Operations Report, the Well Termination Record and the Change of Well Status for the Bovie J-76 well. The reports have been reviewed and satisfy the requirements of section 89(1) of the *Oil and Gas Drilling and Production Regulations*.

Our records have been updated identifying the status of the well as Abandoned and in compliance with the Downhole Well Abandonment Requirements (Section 6A) of the *Well Suspension and Abandonment Guidelines and Interpretation Notes*.

Sincerely,



Pauline de Jong

Chief Conservation Officer

- c Richard Bean, Superintendent – ARO, Paramount Resources Ltd.
Tim Wood, Manager, Drilling Completions, Paramount Resources Ltd.