

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Jean Marie B-48	Operator:	Imperial Oil Limited
Location of Inspection:	62° 27' 10" N 120° 38' 16" W	Access method:	Helicopter
Site Contractor:	N/A	Status:	Non-compliant suspended
Approval Info	ACW-2021-IMP-B-48-WID 0448	WID:	0448
Date of Inspection	22-FEB-2022	H2S Site:	No

Summary of Inspection

Activity on site	N/A		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	N	Site access is restricted by limited size of cleared area at the wellsite (See Photo #1) Wind indicator post and frame installed at the site, however, wind indicator not functional as no windsock present. (See Photo #1)	
Well Head Access	Y	Encroachment of brush near the well. (See Photo #1)	
Signage	N/A	Unable to confirm well identification signage in place due to snow cover.	
General Housekeeping	Y	No debris noted on site above snow cover.	
SCV Open and dead	N/A		

Additional Site Hazards:

At the time of the inspection the size of the cleared area around the well along with some brush encroachment is restricting site access. The alternate landing site is a significant distance from the well site with no sight lines between the two.

There was no functional wind indicator installed on the site.

Section 5A of the *Well Suspension and Abandonment Guidelines and Interpretation Notes* states "All wellheads must be safely accessible for inspection and monitoring".

The well site must allow for year-round access to inspect and monitor including winter months when there may be significant snow depth on the ground. This includes the requirements to:

- Maintain the wellsite to allow rotary wing aircraft to land at a safe distance upwind of the well head;
- Ensure safe ingress, egress and access to the well head and valves for inspection and monitoring; and
- Install a wind indicator.

Comments and Summary:

Aerial inspection only.

Documents Requested/ Collected:

N/A

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 and C-004 / Brian Heppelle S-001/C-005

Inspected By



Signature of OROGO Chief Safety Officer

18-MAR-2022

Date Signed



Photo #1: Aerial view of Jean Marie B-48.