

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Mount Coty 2K-02	Operator:	Prairie Provident Resources Canada Ltd.
Location of Inspection:	60° 11' 34" N 123° 31' 14" W	Access method:	Helicopter
Site Contractor:	N/A	Status:	Suspended
Approval Info	ACW-2021-PPR-WID1993 Variation # 3	WID:	1993
Date of Inspection	23-FEB-2022	H2S Site:	Yes - 0.005 ppm

Summary of Inspection

Activity on site	N/A		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y		
Well Head Access	Y	Well head was removed, and wellbore cut and capped at time of inspection. (See Photo #1)	
Signage	Y	Well identification abandonment sign installed in (See Photo #2)	
General Housekeeping	Y		
SCV Open and dead	N/A		

Additional Site Hazards:

None observed

Comments and Summary:

Well abandonment operations had just been completed at the time of the inspection.

Signage and site conditions were compliant with the *Well Suspension and Abandonment Guidelines and Interpretation Notes*.

Documents Requested/ Collected:

N/A

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 and C-004 / Brian Heppelle S-001/C-005

Inspected By

18-MAR-2022

Date Signed



Signature of OROGO Chief Safety Officer



Photo #1: Aerial view of Mount Coty 2K-02.



Photo #2: Well Identification Sign – Mount Coty 2K-092