

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	S. Pointed Mountain L-68	Operator:	Prairie Provident Resources Canada Ltd.
Location of Inspection:	60° 11' 34" N 123° 31' 9" W	Access method:	Helicopter
Site Contractor:	N/A	Status:	Non-compliant suspended
Approval Info	ACW-2021-PPR-L-68-WID1207	WID:	1207
Date of Inspection	23-FEB-2022	H2S Site:	No

Summary of Inspection

Activity on site	N/A		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y		
Well Head Access	Y		
Signage	Y	(See Photo #4)	
General Housekeeping	Y	No debris noted on site above snow cover.	
SCV Open and dead	N	Reported SCV flow. Fluid containment, monitoring and flow measurements previously implemented as per OROGO requirements.	

Additional Site Hazards:

Prairie Provident Resources Ltd. reported non-serious surface casing vent flow.

8m³ tank tied into the surface casing vent to intercept any produced fluids from the SCV appears to have sufficient freeboard (See Photo #2).

A methane smell was noted as the inspectors approached the well.

Comments and Summary:

The well site appeared to be in good condition and free of vegetation (See Photo #1).

A wind indicator was installed on the well head to ensure safe upwind approach (see Photo #2)

Rig matting was staged at the well site entrance for planned future abandonment operations.

Documents Requested/ Collected:

N/A

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004/C-004 and Brian Heppelle S-001/C-005

Inspected By



Signature of OROGO Chief Safety Officer

18-MAR-2022

Date Signed



Photo #1: Aerial view of S. Pointed Mountain L-68.



Photo #2: S. Pointed Mountain L-68 well head with SCV connected to tank to collect any liquids.



Photo#3: S. Pointed Mountain L-68 rig matting staged at well site entrance.



Photo#4: S. Pointed Mountain L-68 Signage.