

---

# OROGO Well Abandonment Verification Inspection Summary Report

---

## Well Information

Well name/ Facility: Cameron A-68

4 digit WID/ Facility Name: 1746

Operator: Strategic Oil Gas

Well status: Abandoned

Coordinates (*NAD 83; decimal degrees; verified onsite*)

Lat: 60.1181

Long: -117.4381

---

## Inspection Date and Contact Information

Date of inspection: 2024-09-19

Access method: Helicopter

OROGO Inspector(s): Michael Martin – Chief Safety Officer/Chief Conservation Officer

---

## Activity Inspected

OA#: OA-2018-003-SOG

ACW# (If applicable):

ACW-2021-SOG-A-68-WID1746

Contractor on site:  N/A

Name:

Company:

Phone:

Email:

---

## Inspection Results

### Site – Safety/Environment

Equipment, infrastructure or debris on site found during inspection?

Yes  No

**If yes, provide details:** Cellar was not removed during abandonment operations (Photo #2). Well abandonment sign was not installed in accordance with section 6E of the *Well Suspension and Abandonment Guidelines and Interpretation Notes* (Photo #2).

Additional clean up required?  Yes  No

**If yes, provide details:**

The open excavation and cellar poses a risk to public safety and the environment as they are not readily seen or backfilled. As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of this excavation is required to be submitted to OROGO no later than December 15, 2024.

The well abandonment sig needs to be reinstalled in accordance with section 6E of the *Well*

Earth works related to decommissioning of facilities and infrastructure posing risk to public safety or the environment identified during inspection?

Yes  No

**If yes, provide details:**

Well center appears not to have been backfilled as part of the well abandonment operations (See Photo #2).

Contamination associated with historic or decommissioning operations identified during inspection?

Yes  No

**If yes, provide details:**

*Suspension and Abandonment Guidelines and Interpretation Notes.*

---

## Photographs

Number of photographs attached: 2

---

## Additional Comments / Observations

As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of this excavation is required to be submitted to OROGO no later than December 15, 2024

---

This inspection was conducted under the *Oil and Gas Operations Act* and associated regulations.

Name: Michael Martin

Designation: Chief Safety Officer / Chief Conservation Officer

ID number: S-004/C-004

Date: 2024-10-25

Signature:



Name:

Designation:

ID number:

Date: Click or tap to enter a date.

Signature:

---

## Photographs

---



**Photo #1:** Cameron A-68 (WID1746) – Aerial view of well site.



**Photo 2:** Cameron A-68 (WID1746) – Open excavation at well center, cellar still in place and improperly installed well abandonment sign.