
OROGO Well Abandonment Verification Inspection Summary Report

Well Information

Well name/ Facility: Cameron B-25

4 digit WID/ Facility Name: 1756

Operator: Strategic Oil and Gas Ltd.

Well status: Abandoned

Coordinates (*NAD 83; decimal degrees; verified onsite*)

Lat: N60.06806°

Long: W117.57953°

Inspection Date and Contact Information

Date of inspection: 2024-09-18

Access method: Helicopter

OROGO Inspector(s): Brandon Bradbury – Safety Officer/Conservation Officer

Activity Inspected

OA#: OA-2018-003-SOG

ACW# (If applicable):

ACW-2022-SOG-B-25-WID1756

Contractor on site: N/A

Name:

Company:

Phone:

Email:

Inspection Results

Site – Safety/Environment

Equipment, infrastructure or debris on site found during inspection?

Yes No

Earth works related to decommissioning of facilities and infrastructure posing risk to public safety or the environment identified during inspection?

Yes No

If yes, provide details: Well center must be properly backfilled and mounded to prevent the ponding of water (Photo #2) **as noted in the September 25, 2024 notice by OROGO**

Additional clean up required? Yes No

If yes, provide details: The open excavation poses a risk to public safety and the environment as they are not readily seen or backfilled. As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of this excavation is required to be submitted to OROGO no later than December 15, 2024

Version: October 15, 2024

Contamination associated with historic or decommissioning operations identified during inspection?

Yes No

If yes, provide details:

Photographs

Number of photographs attached: 2

Additional Comments / Observations

As seen in Photo #2, the well sign has been bent over and may be on its way to falling off. This well sign is not satisfactorily installed and must be installed in a permanent manner as per section 6E of the *Well Suspension and Abandonment Guidelines and Interpretation Notes*

As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of these pilings is required to be submitted to OROGO no later than December 15, 2024.

This inspection was conducted under the *Oil and Gas Operations Act* and associated regulations.

Name: Brandon Bradbury

Name:

Designation: Safety Officer/Conservation Officer

Designation:

ID number:

ID number:

Date: 2024-10-18

Date: Click or tap to enter a date.

Signature:



Signature:



Photo #1 Aerial view of Cameron B-25 well site.



Photo #2 Close up view of the well center which has not been backfilled and mounded to prevent the ponding of water. The well sign is also bent over and may fall off in the near future.