



November 28, 2023

**Office of the Regulator of Oil and Gas Operations**

PO Box 1320, Yellowknife, NT X1A 2L9

[Pauline\\_DeJong@gov.nt.ca](mailto:Pauline_DeJong@gov.nt.ca); [Mike\\_Martin@gov.nt.ca](mailto:Mike_Martin@gov.nt.ca); [orogo@gov.nt.ca](mailto:orogo@gov.nt.ca)

**RE: Well Inspection Reporting – Cameron F-73 – OA-2018-003-SOG**

As you are aware, on January 28, 2020 (the “**Receivership Date**”), the Court of Queen’s Bench of Alberta (the “**Court**”) granted an Order pursuant to section 243 of the Bankruptcy and Insolvency Act, RSC 1985, c. B-3 and section 13(2) of the Judicature Act, RSA 2000, c. J-2, whereby Alvarez and Marsal Canada Inc. (the “**NWT Receiver**”) was appointed Receiver, without security, of all of the current and future assets, undertakings and properties of Strategic Oil and Gas Ltd. and Strategic Transmission Ltd. (collectively, “**Strategic**” or the “**Company**”) situated in the Northwest Territories (the “**NWT Property**”). For further information on the Receivership proceedings, please visit the NWT Receiver’s website at: [www.alvarezandmarsal.com/sog](http://www.alvarezandmarsal.com/sog).

The NWT Receiver, the Government of the Northwest Territories and ELM Inc. (“**ELM**”) entered into an abandonment agreement for the purposes of completing the abandonment work required by the office of the Regulator of Oil and Gas Operations (“**OROGO**”).

The NWT Receiver respectfully endorses the submission made by ELM to OROGO for the purposes of this inspection report.

Should you have any questions or require further information, please contact the undersigned at [dmacrae@alvarezandmarsal.com](mailto:dmacrae@alvarezandmarsal.com).

Yours truly,

A handwritten signature in grey ink, appearing to be 'D. Macrae'.

**Alvarez & Marsal Canada Inc., in its capacity as Receiver of  
Strategic Oil & Gas Ltd. and Strategic Transmission Ltd.’s NWT Properties  
and not in its personal or corporate capacity**

cc: Christopher Gagnon [Christopher@elminc.ca](mailto:Christopher@elminc.ca)

*Encl.*

November 28, 2023

**Office of the Regulator of Oil and Gas Operations**  
PO Box 1320  
Yellowknife NT, X1A 2L9

By Email: [orogo@gov.nt.ca](mailto:orogo@gov.nt.ca)

**RE: Site Inspection – Cameron F-73 (ACW-2022-SOG-F-73 WID 1992)**

ELM Inc, acting on behalf of Alvarez & Marsal Canada Inc in their capacity as the receiver for Strategic Oil and Gas Ltd has completed an inspection on the above mentioned well. This well was fully abandoned in Q1 of 2023. Enclosed is the following documents for the inspection on this well.

1. Well site inspection form
2. Photographs from inspection
3. Wellbore diagram

Should you have any questions or require further information, please contact the undersigned at [christopher@elminc.ca](mailto:christopher@elminc.ca)

Sincerely,

Christopher Gagnon, EIT

ELM Inc, acting as a consultant to Alvarez & Marsal Canada Inc

---

## Well Inspection Report

---

### Instructions

- Complete all pages.
- Sign and submit electronically within 30 days of the well inspection to [orogo@gov.nt.ca](mailto:orogo@gov.nt.ca).
- If you wish to submit a hard copy, please use the courier address at [www.orogo.gov.nt.ca/contact-us](http://www.orogo.gov.nt.ca/contact-us).
- Refer to the [Well Suspension and Abandonment Guidelines and Interpretation Notes](#) (May 2022) for details on well inspection requirements.
- Report in metric units.

#### Required attachments:

- Photos of wellhead and well site (*Include descriptions*)  
# of photos attached: 15 (includes 2F-73)
- Wellhead schematic
- Wellbore schematic

---

### Well Information

Well name: Strategic et al Cameron F-73

4 digit WID: 1992

OROGO risk level: Level 2

Wellhead?  Yes  No

Pressure rating of all wellhead components: None

Pumpjack?  Yes  No

Operator: Strategic Oil & Gas Ltd

Well status: Abandoned

Coordinates (*In decimal degrees; verified onsite*)

Datum:  NAD 27  NAD 83  Unknown

Lat: 60.0400

Long: -117.4928

Completed in H<sub>2</sub>S zone? No

Estimated % of H<sub>2</sub>S: Click or tap here to enter text. or

Measured % of H<sub>2</sub>S: Click or tap here to enter text.

---

### Inspection Date and Contact Information

Date of inspection: 2023-10-18

Date of previous inspection: Click or tap to enter a date.

Inspection conducted by:

Name: Matt Ewanchuk

Company: ELM Inc

Phone: 4038722418

Email: [mewanchuk1414@gmail.com](mailto:mewanchuk1414@gmail.com)

---

### Environmental or Safety Concerns

(Report all incidents as required under section 75 of the Oil and Gas Drilling and Production Regulations)

Environmental or safety concerns?  Yes  No

If yes, provide details: Click or tap here to enter text.

## Inspection Results

### Site

Well site accessible for inspection and monitoring?  Yes  No

Equipment or debris on site?  Yes  No

Additional clean up required?  Yes  No

Provide details of all site accessibility concerns: Cleaned up metal debris, rags, and tools that were lost in the snow.

Brush cleared 25 m around wellhead?  Yes  No

Wind indicator present and functional?  Yes  No

### Wellhead

Wellhead accessible for inspection and monitoring?  Yes  No

Valves chained and locked?  Yes  No

Valves operate freely?  Yes  No

Pressure test well head seal assembly?  Yes  No

*(If yes, provide details in comments section with supporting documentation)*

Surface casing vent open, operable and accessible in all seasons?  Yes  No

Pumpjack secure?  Yes  No  N/A

Visible marker or fence in place?  Yes  No  
4-digit Well ID, operator and contact information up to date?  Yes  No

Date of previous well head seal assembly pressure test: [Click or tap to enter a date.](#)

### Surface Casing Vent Flow (SCVF) / Gas Migration (GM) testing

Evidence of SCVF?  Yes  No

SCVF test conducted?  Yes  No  
*(If yes, provide details in comments section with supporting documentation)*

Signs of GM?  Yes  No

GM test conducted?  Yes  No  
*(If yes, provide details in comments section with supporting documentation)*

Gas samples taken?  Yes  No  
*(If yes, provide details in comments section identifying location and anticipated date of submission of analysis to OROGO)*

### Shut-in pressures

Production casing pressure (kPa):  
n/a

Intermediate casing pressure (kPa):  
n/a

Production tubing pressures (kPa):  
n/a

Any other readings taken:  
Well cut and capped

---

## Comments

- Details of:  SCVF/ GM testing (*Include source: SCV, wellbore or soil vapour*)  
 Shut-in pressures (*Include equipment used, results, any changes from previous inspections and previous inspection dates*)  
 Seal assembly testing (*Include maximum pressure tested and duration of test*)  
 Other comments

Well was cut and capped in March 2, 2023. GM testing was previously completed and submitted as part of the application to abandon the well. Confirmation of change of well status was received from OROGO on June 9, 2023 certifying this well as abandoned.

Abandoned well sign was installed with a significant amount of ice on site, thus it was not dug very deep into actual soil. Not much is keeping the sign standing up.

Additional supporting documentation attached?  Yes  No

If yes, list attached documentation: Pictures.

---

I certify based on personal knowledge of well inspection operations undertaken at the above named well that the above information is accurate.

Responsible Officer:

Name: Duncan MacRae  
Title: Vice President  
Operator: Alvarez & Marsal Canada Inc., in its  
capacity as receiver of Strategic Oil & Gas's  
NWT Property

Date: 12/01/2023

Signature:



---

**CAMERON F-73 and CAMERON 2F-73**



**North at F-73 well centre**



**East at F-73 well centre**



**South at F-73 well centre**



**West at F-73 well centre**


**CAMERON F-73 and CAMERON 2F-73**



**North at 2F-73 well centre**



**East at 2F-73 well centre**



**South at 2F-73 well centre**



**West at 2F-73 well centre**


## CAMERON F-73 and CAMERON 2F-73



**Northeast view from helicopter**



**East view from helicopter**



**South view from helicopter**



**West view from helicopter**

**CAMERON F-73 and CAMERON 2F-73**



**F-73 Abandoned well sign**



**2F-73 Abandoned well sign**



**Garbage picked up off site**

