
OROGO Well Abandonment Verification Inspection Summary Report

Well Information

Well name/ Facility: Cameron 2H-03
4 digit WID/ Facility Name: 2073

Operator: Strategic Oil Gas
Well status: Abandoned

Coordinates (*NAD 83; decimal degrees; verified onsite*)

Lat: 60.00391
Long: -117.5031

Inspection Date and Contact Information

Date of inspection: 2024-09-17
Access method: Helicopter

OROGO Inspector(s): Michael Martin – Chief Safety Officer/Chief Conservation Officer

Activity Inspected

OA#: OA-2018-003-SOG
ACW# (If applicable):
ACW-2023-SOG-2H-03-WID2073

Contractor on site: N/A

Name:
Company:
Phone:
Email:

Inspection Results

Site – Safety/Environment

Equipment, infrastructure or debris on site found during inspection?
 Yes No

If yes, provide details: 11 hollow pilings were identified on site. These pilings were cut just above ground level and visually obscured by vegetation (See Photo #1 and #2).

- 2 Pilings – 20" diameter
- 8 Pilings – 18" diameter
- 1 piling – 6" diameter

Some debris was also located on site that requires removal (See Photo #3).

Additional clean up required? Yes No

If yes, provide details: Remaining pilings pose a risk to public safety and the environment as they are hollow and not readily seen. As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of these pilings is required to be submitted to OROGO no later than December 15, 2024.

Site debris should be collected and removed from site upon the next visit to site by SOG.

Version: October 15, 2024

Earth works related to decommissioning of facilities and infrastructure posing risk to public safety or the environment identified during inspection?

Yes No

If yes, provide details:

Contamination associated with historic or decommissioning operations identified during inspection?

Yes No

If yes, provide details:

Photographs

Number of photographs attached: 3

Additional Comments / Observations

As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of these pilings is required to be submitted to OROGO no later than December 15, 2024.

This inspection was conducted under the *Oil and Gas Operations Act* and associated regulations.

Name: Michael Martin

Name:

Designation: Chief Safety Officer / Chief Conservation Officer

Designation:

ID number: S-004/C-004

ID number:

Date: 2024-10-15

Date: Click or tap to enter a date.

Signature:

Signature:



Photographs



Photo #1: Cameron 2H-03 (WID2073) – 11 identified unsecured pilings circled in red



Photo 2: Cameron 2H-03 (WID2073) – 18" Unsecured piling



Photo #3: Cameron 2H-03 (WID2073) – Debris (Wellhead Valve) on site requiring removal.