

Incident #	INC-2023-004-SOG-OA-2018-003	
Incident occurred on:	February 18 th , 2023	
OA/ACW #:	ACW-2023-SOG-C-75-WID1793	
Operator:	Strategic Oil and Gas	
Location:	Cameron C-75 (WID 1793)	
Summary of incident:	Fall from height – Fractured foot.	
Incident reported to OROGO by the operator on:	February 18 th , 2023	
Incident reported to NT-NU Spill Line (if required) on:	N/A	
Operator Follow-up Investigation Report:	Due: March 10 th , 2023 Received:	
Status:	<p>February 18th, 2023: While running a cement bond log under pressure to close a micro annulus on the outside of the casing, the wireline tool was near the lubricator. The floor hand loosened the flange while the wellbore was still pressurized and was knocked off the rig floor and onto the ground surface below resulting in a fractured foot.</p> <p>Worker was medevacked to High Level for assessment and may need to go to Edmonton for further assessment.</p> <p>March 10th, 2023:</p> <p>FILE OPEN</p>	
	Brandon Bradbury – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.