

## WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	F-73 and 2F-73/Cameron Hills	Operator:	Strategic Oil and Gas Ltd.
Location of Inspection:	Cameron Hills Production Field	Access method:	Helicopter – Great Slave Helicopters
Site Contractor:	None	Status:	Compliant Suspended– Production Wells
Approval Info	OA-2018-003	WID:	1992/2025
Date of Inspection	12/SEP/2019	H2S Site:	Yes

### Summary of Inspection

<b>Activity on site</b>	Gas migration testing and annual well inspections conducted by GChem (Contractor)		
<b>Conditions</b>	<b>Satisfactory (Y/N)</b>	<b>Comments</b>	
Site Access	Y		
Well Head Access	Y		
Signage	N	Well sign has incorrect contact phone number. (Photo #2) Well sign should be updated with correct contact phone number.	
General Housekeeping	Y		
SCV Open and dead	Y	0 Bubbles in 10 min at SCV.	

#### Additional Site Hazards:

Potential of H2S Gas exposure, personal monitors worn by inspectors.  
Signs of wildlife (tracks and scat)

#### Comments and Summary:

OROGO Inspection Team: Brian Heppelle (Chief Safety Officer), Pauline de Jong (Chief Conservation Officer) and Michael Martin (Safety Officer).

#### Documents Requested/ Collected:

Photos and notes taken on site.

**Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.**

Michael Martin S-004 / Brian Heppelle S-001/Pauline de Jong C-002

Inspected By



Signature of OROGO Chief Safety Officer

2019-12-20

Date Signed

**DIIMS # 89027894**

**DIIMS # 89027905**



Photo # 1: Well Site




Photo #2: Well sign has incorrect emergency contact phone number. Well sign should be updated with correct contact phone number