

WELLSITE SUMMARY INSPECTION REPORT

| | | | |
|-------------------------|--------------------------------|----------------|--------------------------------------|
| Well/Facility Name: | J-62/Cameron Hills | Operator: | Strategic Oil and Gas Ltd. |
| Location of Inspection: | Cameron Hills Production Field | Access method: | Helicopter – Great Slave Helicopters |
| Site Contractor: | None | Status: | Non-compliant – Production Well |
| Approval Info | OA-2018-003 | WID: | 1158 |
| Date of Inspection | 12/SEP/2019 | H2S Site: | Yes |

Summary of Inspection

| | | | |
|-------------------------|---|--|--|
| Activity on site | Gas migration testing and annual well inspections conducted by GChem (Contractor) | | |
| Conditions | Satisfactory (Y/N) | Comments | |
| Site Access | Y | Wind indicator requires repair (Photo # 1) | |
| Well Head Access | Y | | |
| Signage | Y | | |
| General Housekeeping | Y | | |
| SCV Open and dead | Y | 0 Bubbles in 10 min at SCV. | |

Additional Site Hazards:

Potential of H2S Gas exposure, personal monitors worn by inspectors.
Signs of wildlife (tracks and scat)

Comments and Summary:

OROGO Inspection Team: Brian Heppelle (Chief Safety Officer), Pauline de Jong (Chief Conservation Officer) and Michael Martin (Safety Officer).

Documents Requested/ Collected:

Photos and notes taken on site.

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 / Brian Heppelle S-001/Pauline de Jong C-002

Inspected By



Signature of OROGO Chief Safety Officer

2019-12-20

Date Signed



Photo # 1: Well Site - Wind indicator requires repair