

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	K-74/Cameron Hills	Operator:	Strategic Oil and Gas Ltd.
Location of Inspection:	Cameron Hills Production Field	Access method:	Helicopter – Great Slave Helicopters
Site Contractor:	None	Status:	Compliant Suspended – Production Well
Approval Info	OA-2018-003	WID:	1972
Date of Inspection	12/SEP/2019	H2S Site:	Yes

Summary of Inspection

Activity on site	Gas migration testing and annual well inspections conducted by GChem (Contractor)		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y		
Well Head Access	Y		
Signage	Y		
General Housekeeping	Y		
SCV Open and dead	Y	0 Bubbles in 10 min at SCV.	

Additional Site Hazards:

Potential of H₂S Gas exposure, personal monitors worn by inspectors.
Signs of wildlife (tracks and scat)

Comments and Summary:

OROGO Inspection Team: Brian Heppelle (Chief Safety Officer), Pauline de Jong (Chief Conservation Officer) and Michael Martin (Safety Officer).

Documents Requested/ Collected:

Photos and notes taken on site.

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 / Brian Heppelle S-001/Pauline de Jong C-002

Inspected By



Signature of OROGO Chief Safety Officer

2019-12-20

Date Signed



Photo # 1: Well Site