

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Cameron J-37	Operator:	Strategic Oil and Gas Ltd. (SOG)
Location of Inspection:	Cameron Hills	Access method:	Helicopter
Site Contractor:	None	Status:	Compliant Suspended – Production Well
Approval Info	OA-2018-003	WID:	1751
Date of Inspection	10/SEP/2020	H2S Site:	Yes

Summary of Inspection

Activity on site	Last company well inspection conducted by SOG September 28, 2018		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y	See Photo #1	
Wellhead Access	Y		
Signage	Y	See Photo #2	
General Housekeeping	Y		
SCV Open and dead	Y	0 Bubbles observed in 10 min	

Additional Site Hazards:

Potential of H2S gas exposure, personal monitors worn by inspectors.

Comments and Summary:

OROGO Inspection Team: Michael Martin (Chief Safety Officer) and Brian Heppelle (Safety Officer/Conservation Officer)

Pilings on site (Photo #3) were noted on file for future reference

Documents Requested/ Collected:

Photos and notes taken on site.

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 / Brian Heppelle S-001

Inspected By

September 29, 2020

Date Signed



Signature of OROGO Chief Safety Officer



Photo #1: Aerial view of J-37



Photo # 2: J-37 Wellhead chained and locked with sign in place



Photo #3: Pilings in place on J-37 well site.