

WELL INSPECTION REPORT

INSTRUCTIONS:

1. Complete both pages.
2. Send one electronic copy of this form and supporting technical documentation by email to orogo@gov.nt.ca. If you wish to communicate with OROGO in hard copy, please do so using the courier address found at www.orogo.gov.nt.ca.

WELL INFORMATION

Well Name: N-06 60-10, 117-30

Coordinates: <i>(verify onsite)</i>	Lat: 60° 5' 50"	Long: 117° 31' 17"
	Datum: Select	

Well Operator: Alvarez and Marsal

Status: Suspended

Current Inspection Date: September 16, 2020

WID: N000002067

Previous Inspection Date: September 27, 2018

Completed in H₂S zone? Select % of H₂S:

EVALUATION

Site

Accessible for inspection and monitoring? Yes; Winter roads or Helicopter

Equipment or debris on site? No;

Additional clean up required? No;

Any environmental or safety concerns? (see Note 1) No;

Number of photos attached? (required) 6 (wellhead, valves, signage and site area, other)

Wellhead

Wellhead accessible for inspection and monitoring? Yes; Winter roads or Helicopter

Brush cleared 10m around wellhead? Yes;

Visible well marker in place? Yes;

Wellhead chained and locked? Yes;

Pumpjack secure? No; Not Applicable

Wellhead valves operate freely? Yes; All well head valves greased

Surface casing vent open? Yes;

Pressure test well head seal assembly? No;

Pressure rating of all components: 5000 PSI

Wellhead schematic attached? (required) No;

OROGO use only

The details of this document have been examined and verified by:

Job Designation _____

Well Identifier _____

Signature _____

Approval Authority

Unique Well Identifier 30 / _____ - _____ - _____ / _____
(eg. 300 / A01 60-00 120-00 / 0)

Date _____



Lat / Long	Invalid LSD	UTM N/E
60° 5' 49.66"	Bearing: 346° (TN) GPS: ±4 m	6662343 m
-117° 31' 18.49"	September 16, 2020 15:24:07	470981 m
Elev: 705 m		CM: -117



N-06 Well Site Inspection
Tubing Pressure

Lat / Long	Invalid LSD	UTM N/E
60° 5' 49.71"	Bearing: 325° (TN) GPS: ±6 m	6662344 m
-117° 31' 18.59"	September 16, 2020 15:24:31	470979 m
Elev: 709 m		CM: -117



N-06 Well Site Inspection
Tubing Pressure



Lat / Long	Invalid LSD	UTM N/E
60° 5' 49.63"	Bearing: 112° (TN) GPS: ±48 m	6662342 m
-117° 31' 18.64"	September 16, 2020 15:47:42	470978 m
Elev: 697 m		CM: -117



N-06 Well Site Inspection