

WELL INSPECTION REPORT

INSTRUCTIONS:

1. Complete both pages.
2. Send one electronic copy of this form and supporting technical documentation by email to orogo@gov.nt.ca. If you wish to communicate with OROGO in hard copy, please do so using the courier address found at www.orogo.gov.nt.ca.

WELL INFORMATION

Well Name: B-38 60-10, 117-30

Coordinates: <i>(verify onsite)</i>	Lat: 60° 7' 13"	Long: 117° 36' 24"
	Datum: Select	

Well Operator: Alvarez and Marsal

Status: Suspended

Current Inspection Date: September 25, 2020

WID: 2002

Previous Inspection Date: September 27, 2009

Completed in H₂S zone? Select % of H₂S:

EVALUATION

Site

Accessible for inspection and monitoring? Yes; Winter roads or Helicopter

Equipment or debris on site? No;

Additional clean up required? No;

Any environmental or safety concerns? (see Note 1) No;

Number of photos attached? (required) 9 (wellhead, valves, signage and site area, other)

Wellhead

Wellhead accessible for inspection and monitoring? Yes; Winter roads or Helicopter

Brush cleared 10m around wellhead? Yes;

Visible well marker in place? Yes;

Wellhead chained and locked? Yes;

Pumpjack secure? No; Not Applicable

Wellhead valves operate freely? Yes; All well head valves greased

Surface casing vent open? Yes;

Pressure test well head seal assembly? No;

Pressure rating of all components: 5000 PSI

Wellhead schematic attached? (required) No;

OROGO use only

The details of this document have been examined and verified by:

Job Designation _____

Well Identifier _____

Signature _____

Approval Authority

Unique Well Identifier 30 / _____ - _____ - _____ / _____
(eg. 300 / A01 60-00 120-00 / 0)

Date _____

Lat / Long Invalid LSD UTM N/E
60° 7' 13.87" 651 m South 332 m West 6664988 m
-117° 36' 24.39" Bearing: 14° (TN) GPS: ±6 m 466279 m
Elev: 719 m September 25, 2020 13:51:13 CM: -117



B-38 Well Inspection
Well Head Sign

Lat / Long Invalid LSD UTM N/E
60° 7' 13.71" 651 m South 332 m West 6664983 m
-117° 36' 24.42" Bearing: 291° (TN) GPS: ±6 m 466278 m
Elev: 726 m September 25, 2020 13:46:44 CM: -117



B-38 Well Inspection
Tubing Pressure

Lat / Long Invalid LSD UTM N/E
60° 7' 13.89" 651 m South 332 m West 6664989 m
-117° 36' 24.38" Bearing: 328° (TN) GPS: ±6 m 466279 m
Elev: 727 m September 25, 2020 13:40:59 CM: -117



B-38 Well Inspection
Casing Pressure

Lat / Long Invalid LSD UTM N/E
60° 7' 13.81" 651 m South 332 m West 6664986 m
-117° 36' 23.91" Bearing: 8° (TN) GPS: ±6 m 466286 m
Elev: 723 m September 25, 2020 13:52:26 CM: -117



B-38 Well Inspection

Lat / Long Invalid LSD UTM N/E
60° 7' 14.00" 651 m South 332 m West 6664992 m
-117° 36' 23.80" Bearing: 158° (TN) GPS: ±8 m 466288 m
Elev: 715 m September 25, 2020 13:51:43 CM: -117



B-38 Well Inspection

Lat / Long Invalid LSD UTM N/E
60° 7' 9.69" 651 m South 332 m West 6664858 m
-117° 36' 22.69" Bearing: 351° (TN) GPS: ±12 m 466304 m
Elev: 777 m September 25, 2020 13:31:11 CM: -117



B-38 Well Inspection

Lat / Long Invalid LSD UTM N/E
60° 7' 14.03" 651 m South 332 m West 6664993 m
-117° 36' 24.53" Bearing: 355° (TN) GPS: ±6 m 466277 m
Elev: 720 m September 25, 2020 13:53:15 CM: -117



B-38 Well Inspection