

2021 Annual Production and Safety Report

For

The Liard (Dehcho) Area
Within
The Northwest Territories
OA-2020-001-PAR

March 30th, 2022



Suite 2800, 421 7 Avenue S.W.
Calgary, Alberta T2P 4K9
Ph: (403) 290-3600
Fax: (403) 290-3614

Table of Contents

1. Introduction
2. Overview of Drilling/Service and Construction Activities for the Fort Liard (Dehcho) area
 - 2.1. Road Construction
 - 2.2. Drilling Activities
 - 2.3. Service Rig Activities
 - 2.4. Construction Activities
3. Overview of Drilling/Service and Construction Activities for the Fort Liard (Dehcho) area
 - 3.1. Suspended Well Inspections
 - 3.2. OROGO Inspections
4. Summary
 - 4.1. Summary of Lost or Restricted Workday Injuries
 - 4.2. Minor Injuries and Safety Related Incidents
 - 4.3. Total Person-Hours

1. INTRODUCTION

The Annual Safety Report

The Annual Safety Report is required pursuant to Part II Section 87 of the Oil and Gas Drilling and Production Regulations:

The Operator shall ensure that, not later than March 31 of each year, an annual safety report relating to the proceeding year is submitted to the Board and includes:

- (a) a summary of lost or restricted workday injuries, minor injuries and safety-related incidents and near-misses that have occurred during the preceding year; and*
- (b) a discussion of efforts undertaken to improve safety.*

Liard (Dehcho) Operating Area

This area is not producing, and the production operations have been suspended. Affected Parties consultations, suspended well inspections, environmental monitoring and winter road construction was conducted in 2021.

2. OVERVIEW OF DRILLING/SERVICING AND CONSTRUCTION ACTIVITIES FOR THE LIARD EAST (DEHCHO) AREA

2.1. ROAD CONSTRUCTION

Constructed a winter road from British Columbia at the EOG d-36-I/94-O-14 compressor site to Paramount I-02 wellsite and then on to Paramount F-36 wellsite in preparation to conduct well abandonments in 2022. Additional road access was constructed to reclaim previously abandoned sites.

2.2. DRILLING ACTIVITIES

There were no drilling activities during the 2021 reporting period.

2.3. SERVICE RIG ACTIVITIES

There were no service rig activities during the 2021 reporting period.

2.4 Construction Activities

There were no construction activities during the 2021 reporting period.

3. OVERVIEW OF PRODUCTION OPERATIONS ACTIVITIES FOR THE LIARD SOUTH (DEHCHO) AREAS

3.1. SUSPENDED WELL INSPECTIONS

Liard Area:

A suspended well inspection was conducted at Arrowhead River B-41 (WID 1733) during the 2021 reporting period.

3.2. OFFICE OF THE REGULATOR OF OIL AND GAS OPERATIONS (OROGO) INSPECTIONS

No OROGO site inspections were conducted in 2021.

4. SUMMARY

Employer's Annual Hazardous Occurrence Report for Human Resources and Skills Canada and the annual safety statistics summary for GNWT WSCC will be submitted.

4.1. SUMMARY OF LOST OR RESTRICTED WORKDAY INJURIES

There were no lost or restricted work injuries during the 2021 reporting period.

4.2. MINOR INJURIES AND SAFETY RELATED INCIDENTS

There were no minor injuries with one safety incident during the 2021 reporting period as follows:

1. HSE incident at B-41 wellsite: As the worker walked from the helicopter landing location towards the wellsite a willow twig hit their face. The worker was assessed and was okay to resume duties. As an abundance of caution the worker was taken to the hospital for an assessment and no medical treatment was required.

Corrective Action Taken: Discussed the importance of wearing all PPE while traveling to site at the next safety meeting.

4.3 Total Person-Hours

Liard (Dehcho) Area total person-hours worked, both employee and contractor, in 2021 was 2196 person-hrs.